997745

18 June 1965

MEMORANDUM FOR THE RECORD

SUBJECT: Completion of Project 997745, Modified Crank System for 940 MC

The under my guidance has designed Dual Crank Brackets for the 940 MC Light Table. These have been evaluated by PID and PAG as being very acceptable.

It has been recommended to that the head chain used in the drive be changed since chains of this type tend to stretch. A link chain will be used on the production models.

25X1A

25X1A

Quality Assurance Section

Declass Review by NIMA / DoD

25X1A

